


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

P-17

History of original corner establishment:



Original corner established in 1881 by Robb & Graddon.  
 Set post from which:  
 A 1 1/2" Pine brs. S30°E 29 IN.  
 A 4" Pine brs. N85°W 15 IN.

Description of corner evidence found: Searched for, not found, Corner position established by single proportion.

Description of monument and accessories I established to perpetuate the original location of this corner: Set 2 1/4" x 30° aluminum pipe with 2 1/2" aluminum cap rising 6" in dirt mound. Pipe set at slant to West due to large sub-surface tree root.  
 BTs  
 1 1/2" PP brs. N88°W 55.1' marked 1/4 522 BT  
 1 1/2" PP brs. N21°E 48.8' marked 1/4 523 BT

Cap marked  
 T115 R35E  
 1/4  
 522 | 523  
 1989  
 LS1020

I hereby certify the above corner was established as described in Oct. 1989.

REGISTERED PROFESSIONAL LAND SURVEYOR

*George W. Colvin, Jr.*  
 OREGON  
 FEBRUARY 14, 1975  
 GEORGE W. COLVIN, JR.  
 1020

Office of County Surveyor County of Grant  
 State of Oregon, I hereby certify that the within instrument was filed in this office for record on the 1 day of July, 1989  
Robert D. Smith by \_\_\_\_\_  
 (COUNTY OFFICIAL) (DEPUTY)