


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

R-9

History of original corner establishment:

*Original corner established in 1881 by Robb & Graden.*




*Set stone 16x12x5 from which:  
 A 8" black pine brs. N74°E 152 lks  
 A 12" black pine brs. S50°W 23 lks  
 A 12" black pine brs. N40°W 40 lks*

Description of corner evidence found: *Find. drill steel 2" below pavement. Accepted by local surveyors and land owners as corner for many years. Held as corner position.*

Description of monument and accessories established to perpetuate the original location of this corner: *Set 2 1/4" x 7" aluminum pipe with 2 1/2" aluminum cap, in concrete, over existing drill steel.*

*Cap marked*

- Witnesses:*
- A 1/2" x 10" iron rod with 1 1/2" aluminum cap, in pavement, brs. S44°W 41.0'* *CAP MKD. R.M. 5 29*
  - A 1/2" x 10" iron rod, in pavement, with 1 1/2" aluminum cap, brs. N29°W 18.5'* *CAP MKD. R.M. 5 20*
  - A 5/8" x 30" iron rod with 1 1/2" aluminum cap brs. N83°E 109.5'* *CAP MKD. R.M. 5 21*
  - A 5/8" x 30" iron rod with 1 1/2" aluminum cap brs. S32°E 282.2'* *CAP MKD. R.M. 5 28*



*I hereby certify the above corner was perpetuated as described in Aug. 1989.*

**REGISTERED PROFESSIONAL LAND SURVEYOR**

*George W. Colvin, Jr.*

OREGON  
 FEBRUARY 14, 1975  
 GEORGE W. COLVIN, JR.  
 1020

Office of County Surveyor County of Grant  
 State of Oregon I hereby certify that the within instrument was filed in this office for record on the 1 day of Dec, 1989  
*Robert D. Dwyer* by \_\_\_\_\_  
 (COUNTY OFFICIAL) (DEPUTY)

R-9