


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

R-14

History of original corner establishment:

None



Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner: Set 2 1/4" x 30" aluminum pipe with 2 1/2" aluminum cap rising 10" in stone mound.

Cap marked

BTs
 8" PP b/s, N59°W 29.4'
 marked W 1/16 522 BT
 13" PP b/s, S55°W 99.5'
 marked W 1/16 527 BT

W 1/16 - 522
 - 527
 1989
 431020

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

I hereby certify the above corner was established as described in Oct, 1989.

George W. Colvin, Jr.
 OREGON
 FEBRUARY 14, 1975
 GEORGE W. COLVIN, JR.
 1020

Office of County Surveyor County of Grant
 State of Oregon, I hereby certify that the within instrument was filed in this office
 for record on the 1 day of Dec, 1989
Robert H. Beyer by _____
 (COUNTY OFFICIAL) (DEPUTY)