


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Center $\frac{1}{4}$ corner not previously established.



Description of corner evidence found:

Established center $\frac{1}{4}$ corner at intersection of lines between opposite corresponding $\frac{1}{4}$ corners.

See Map of Survey No. 311.

Description of monument and accessories established to perpetuate the original location of this corner

Set a $1\frac{1}{2}$ "x30" iron pipe 26 ins. in the ground with brass cap mkd. as shown.


from which NEW BEARING TREES:

A P. pine 16 ins. diam., bears N.41°E., 50.4 ft., mkd.,
 $C\frac{1}{4}$ S28 CS BT.

A P. pine 15 ins. diam., bears N.57°W., 28.7 ft., mkd.,
 $C\frac{1}{4}$ S28 CS BT.

Surrounded pipe with a mound of stone.

Used compass with 20° East variation and a steel tape, measuring to a nail in a brass washer driven into BT blaze. Washer is mkd. " OPLS 598".



Office of County Surveyor County of Grant
 State of Oregon , I hereby certify that the within instrument was filed in this office
 for record on the 30th day of August; 19 73, at 1:57 o'clock P. m., (signed)
Robert D. Baggett County Surveyor
 (COUNTY OFFICIAL) (DEPUTY)

Witnessed by August 30, 1973
Darlene Lemon

