

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was established by Herman D. Gradon and Bamford Robb, US Deputy Surveyors, during the original joint survey Contract No. 383 dated March, 1881.

Set post in earth mound and dug pits as per instructions for 1/4 sec. cor.

DIAGRAM

T11S
R35E R35 1/2 E
1/4
S25 | S28

1985
PLS 699

Description of corner evidence found:

No evidence of the corner was found. It is in the meadow near several meander channels for the nearby creek. Beavers have done a lot work in the area as well. The corner area is relatively unstable, but no good witness corner location is available, either.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 3 1/4" aluminum cap, marked as shown in the diagram, 20" in the ground in a small creek, at single proportionate measurements from adjacent found corners. Built a mound of rock to be 30" in diameter by 10" high around the monument.

No new bearing trees set because no trees are available.

1" galvanized pipe with 2 1/2" aluminum cap Reference Monument bears S1°W, 34.7 feet marked 1/4 S25 RM ↑

1" galvanized pipe with 2 1/2" aluminum cap Reference Monument bears S87° 30'E, 4.0 feet marked 1/4 S28 RM ←

Set steel fence posts 5 feet N and 5 feet S of the corner on the National Forest property lines. Attached Forest Boundary signs to each post and a Land Survey Monument sign to the N post.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on September 3, 1985, I re-established the corner as herein described.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Leland Lee Myers

OREGON
JULY 9, 1965
LELAND LEE MYERS
699

FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 25 DAY OF Oct, 1985

Robert A. Smith Co. Sur.

See MAP OF SURVEY NO. 901