


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Southwest 1/16th corner not previously established.



Description of corner evidence found:

Established SW 1/16th corner at intersection of lines between opposite corresponding 1/16th corners.

See Map of Survey No. 311.

Description of monument and accessories established to perpetuate the original location of this corner

Set a 1 1/2" x 30" iron pipe 24 inches in the ground with brass cap marked as shown.

from which

NEW BEARING TREES:

A p. pine, 12 ins. diam., bears N.6°E., 13.0 ft., mkd., SW 1/16 S28 CS BT.

A P. pine 12 ins. diam., bears S.30°W., 30.7 ft., mkd., SW 1/16 S28 CS BT.

The corner of wire fences running South and West bears South 10 ft.

Raised a mound of stone to top of pipe.

Used compass with 20° E. variation and steel tape, measuring to a nail in BT blaze. Nail driven into a washer which is marked "OPLS 598".




Office of County Surveyor County of Grant

State of Oregon, I hereby certify that the within instrument was filed in this office

for record on the 30th day of August, 1973, at 1:51 o'clock P.m., (signed)

Robert D. Baggett County Surveyor by _____ (DEPUTY)

Witnessed by Darlene Lemmon August 30, 1973



Robert D. Baggett

