


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

West 1/16th corner between sections 28 and 33 not previously established.



Description of corner evidence found:

Established W 1/16th corner on section line at point midway between the SW corner of section and the South 1/4 corner.

Description of monument and accessories I established to perpetuate the original location of this corner

See Map of Survey No. 311.

Set a 1 1/2" x 30" iron pipe 28 inches in the ground with brass cap marked as shown.

from which


NEW BEARING TREES:

A lodgepole, 10" diam., bears N.27°W., 18.6 ft., mkd., W1/16 S28 CS BT.

A lodgepole, 10" diam., bears S.65°E., 24.6 ft., mkd., W1/16 S33 CS BT.

An old rail fence (fallen down) bears East 4.0 ft., this fence runs north and south.

A new wire fence is 15 ft. west of cor. and runs North and South. Used compass with 20° E. var., and steel tape, measuring to a nail in a brass washer driven into BT blaze. Washer mkd. "OPLS 598".



Office of _____ County Surveyor _____ County of _____ Grant _____
 State of _____ Oregon _____, I hereby certify that the within instrument was filed in this office
 for record on the 30th day of August _____, 1973, at 1:52 o'clock P.m., (signed)
 Robert D. Baggett County Surveyor by _____ (DEPUTY)

Witnessed by Darlene Lemon August 30, 1973

