CERTIFIED RECORD OF LAND CORNER MONUMENTATION

X-9

History of original corner establishment:

Original corner established in 1881 by Robb & Gradon.
Set stone 20x8x6 from which:
A 36" pine brs. N10°W 67 lks.
A 36" pine brs. S75°E 22 lks.

DIAGRAM
T11S R35E
1/4
532 | 533

MOS 1116

Description of corner evidence found: 18x9x7 stone in stone mound marked 1/4 on North face.
No evidence of original BTs.

Description of monument and accessories I established to perpetuate the original location of this corner: Set 2¼"x30" aluminum pipe with 2½" aluminum cap rising 5" in stone mound. Buried original stone alongside.
New BTs:
A 18" PP brs. N44°E 13.6'
marked 1/4 S33 BT
A 13" PP brs. N79°W 42.6'
marked 1/4 S32 BT

Cap marked

T11S R35E
1/4
532 | 533
1989
LS 1020

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
FEBRUARY 14, 1975
GEORGE W. COLVIN, JR.
1020

I hereby certify the above corner was perpetuated as described in July, 1989.

Office of County Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office for record on the 1 day of Dec, 19 89
Robert L Bagett by
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

☆GPO: 1989-692-049

X-9