


CORNER RESTORATION

E $\frac{1}{4}$ corner
CORNER Sec. 5 TWP 12 S RANGE 26 E
ORIGINAL SURVEY BY: Jason Owen
CONTRACT NUMBER: 194
CONTRACT DATE: July 1, 1873



ORIGINAL DESCRIPTION:

S 0° 13' E. on true line between Secs. 4 and 5.
40.28 set stone for $\frac{1}{4}$ sec. cor.

RECEIVED AND
FILED

SEP 18 1979

JOHN LIVEIRA, County Clerk

Amelia Laura Deputy

RESTORATION BY, STAMP AND DATE:

D. I. Griffith
K. Leckenby
L. Mitchell
F. Jackson

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Baggett

OREGON
JULY 12, 1963
ROBERT D. BAGGETT
598

April 25, 1979

Grant County Surveyor

EVIDENCE FOUND:

Found stone 12"x12"x5" marked $\frac{1}{4}$ and set in a mound of stone.

See Map of Survey No. 571.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

I accept the position of the corner stone.

At the corner point: Set 2 $\frac{1}{2}$ "x30" aluminum pipe with National Park Service aluminum cap marked as shown, I buried the corner stone South and alongside the aluminum pipe and surrounded the pipe with a concrete collar and a mound of stone, from which I scribed NEW BEARING TREES:

A 7" Juniper bears S. 40° E., 46.2 ft. mkd. $\frac{1}{4}$ S4BT.

A 7" Juniper bears N. 3° W., 11.3 ft. mkd. $\frac{1}{4}$ S5BT.

I used a magnetic compass with 20° East variation and steel tape, measuring to the center of the bearing trees.

Complete and File with Office of the Grant
County Surveyor, Grant County, Oregon,
Courthouse, Canyon City, Oregon 97820

STANDARD NATIONAL PARK SERVICE
MONUMENT MARKED

