


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established



Description of corner evidence found:

NONE

See map of survey dated January 1985

Description of monument and accessories I established to perpetuate the original location of this corner: At the corner position I set a 2½"x30 inch aluminum pipe with aluminum cap marked as shown, 18 inches in the ground, from which:

New BTs

A 22 inch diameter Juniper bears N68°E 23.3 feet marked C¼ S13 BT
A 12 inch diameter Red Fir bears N9°W 56.1 feet marked C¼ S13 BT

Raised mound of stone around monument


Set steel fenceposts approximately 5 feet East with 54-2 sign and approximately 5 feet North with 54-2 and 54-9 signs attached

Corner set May 16, 1985

Witness: Ray Crapo

Note: this corner was set on the above mentioned survey in which an error in proportioning was discovered. The corner was reset to the proper position at this date, but the cap is marked 1984.

I used a steel tape and magnetic compass in the establishment of these accessories. I used 20° East magnetic declination and the distance to the BTs are to the center of the tree. I set a brass washer marked OPLS 644 at the BT blaze. I painted a 6 inch red band around all BTs and attached 54-3 and 54-9 signs.



REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 10, 1964
DUANE I. GRIFFITH
644
State of

Surveyor
Oregon
County of Grant
I hereby certify that the within instrument was filed in this office
for record on the 11 day of June, 1985
Robert D. Baggett
(COUNTY OFFICIAL)
by
(DEPUTY)