


CORNER RESTORATION

CORNER E1/16 Sec1 TWP12S RANGE 29E
ORIGINAL SURVEY BY: William R. Gradon 028
CONTRACT NUMBER: 497
CONTRACT DATE: 1884




ORIGINAL DESCRIPTION:


None

RESTORATION BY, STAMP AND DATE:

June, 1970



Duane I. Griffith



EVIDENCE FOUND:

None

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

Set $2\frac{1}{2}$ "x30" iron post with Brass Cap Mkd.:


From which:

A fir 10" diam. bears $S47^{\circ}E$, 14.4 ft.
Mkd. E 1/16 S 1 BT

A fir 10" diam. bears $S41^{\circ}W$, 22.0 ft.
Mkd. E 1/16 S 1 BT

MONUMENT MARKED

Grant County Surveyor



Complete and File with Office of the Grant
County Surveyor, Grant County, Oregon,
Courthouse, Canyon City, Oregon 97820

Steel tape & Compass
Var.= 20° East