


CORNER RESTORATION

CORNER E $\frac{1}{4}$ Sec. 1 TWP 12S RANGE 29E

ORIGINAL SURVEY BY: William H. Byars

CONTRACT NUMBER: Unknown

CONTRACT DATE: 1881




ORIGINAL DESCRIPTION:

Set Basalt stone 15"x8"x7"

RESTORATION BY, STAMP AND DATE:

June, 1970



EVIDENCE FOUND:

None

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

Set 2 $\frac{1}{2}$ "x30" iron post with Brass Cap Mkd.:

From which:

A fir 14" diam. bears N23°E, 55.8 ft.


Mkd. $\frac{1}{4}$ S6 BT

A tamarack 12" diam. bears S55°W, 22.8 ft.

Mkd. $\frac{1}{4}$ S1 BT

MONUMENT MARKED

Grant County Surveyor



Complete and File with Office of the Grant
County Surveyor, Grant County, Oregon,
Courthouse, Canyon City, Oregon 97820

Steel tape & Compass
Var.= 20° East