


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. B-7

History of original corner establishment:

No corner monument was originally set.

DIAGRAM



Description of corner evidence found:

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 2½"x30" aluminum pipe with cap stamped:
Set pipe 24" in ground with mound of dirt to cap.

Bearing trees:

A White Fir 8" dia. bears North, 13.2 ft. scribed CN1/16 S5 BT.

A White Fir 10: dia. bears S72°E, 57.0 ft. scribed CN1/16 S5 BT.

T12S R30E
C
N1/16 + S5
C
1982
OR PLS 1294


Attached 54-3 & 54-4 signs to both BT's. Attached brass washer stamped LS 1294 to foot blaze of both BT's. Painted blazes and 6" band around both BT's red.

Attached 54-2 & 54-4 signs to metal post 6 ft. North of corner and 54-2 & 54-9 signs to metal post 6 ft. East of corner.

Magnetic Declination = 19°30'E

I hereby certify the above corner monument was established as herein described on July 8, 1982

Witnesses: R. Orton
G. Orton



Office of..... County Surveyor..... County of..... Grant
State of..... Oregon....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 1982
Robert H. Dugas..... by.....
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

☆ GPO—798-276

SUPERCEDED BY REMON
FILED SEPT 14, 1985