


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. B-7

History of original corner establishment:

Refer to Grant County Record of Survey Map No. 879 for a detailed discussion of the procedures involved in the establishment of the corner position which is described on this remonumentation record. Also refer to Record of Survey Map No. 724 and to the Grant County Corner Remonumentation Records for information related to the prior establishment of this corner.



Description of corner evidence found:

Found the corner monument and accessories as described on the record of Land Corner Monumentation filed for this corner with the Grant County Surveyor during July-August, 1982 in conjunction with Grant County Record of Survey Map No. 724.

Note: The 1981-82 bearing trees described below were found to be alive and in good condition. The tree species, diameter and scribing noted is as described on the 1981-82 record. The existing blazed faces were not modified for direction and do not necessarily face the 1985 corner position.

Description of monument and accessories I established to perpetuate the original location of this corner:


Following the procedures described on Grant County Record Map of Survey No. 879, we remove the monument established in 1981-82 and reset it at the position indicated on Survey No. 879. The monument extends 6" above ground and has the markings "Reset 1985" added to the existing markings, from which the 1981-82 bearing trees:

A White Fir 8" dia. bears N 16°E 31.0 ft. scribed CN 1/16 S5 BT.

A White Fir 10" dia. bears S88°E 62.2 ft. scribed CN 1/16 S5 BT.

Staff Compass (Declination 19°20' East)
Steel Tape
July 8 - 11, 1985

Gary Langlitz
Greg Orton



Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 14 day of Sept, 1985
Robert D. Langlitz by _____
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

SUPERCEDES REMON
filed Aug 6, 1982

☆ GPO 799-509

B-7