

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not preveously established.

DIAGRAM

T12S R30E
NE1/16
S3
1982
PLS 848

Description of corner evidence found:

Corner not preveously established.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 30"x2" aluminum pipe with a 3 1/2" aluminum Cap. stamped as shown in diagram. Set 26" in ground.

From Which

A Fir 12" dia. bears N 25° W 32.7ft. scribed NE 1/16 S3 B.T.

A Pine 16" dia. bears S 59° E 67.2ft. scribed NE 1/16 S3 B.T.

Nailed brass washers stamped PLS 848, bearing tree and warning signs to each tree. Painted 6" red band around each tree.

Set steel posts with boundry and warning signs 5.0ft. South and 5.0ft. West from corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

Corner monumented 10-82

Witnessed by D. Mitchell Ferguson

Office of....Surveyor..... County of.....Grant.....

State of.....Oregon....., I hereby certify that the within instrument was filed in this office

for record on the..29th day of.....August....., 19..83.

Robert D. Bayless

(COUNTY OFFICIAL)

by

(DEPUTY)