

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not preveously established.

DIAGRAM

T12S R30E
S1/16
S4 | S3
1982
PLS 848

Description of corner evidence found:

Corner not preveously established.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set a 30"x2" aluminum pipe with a 3 1/2" aluminum Cap. stamped as shown in diagram, set 20" in ground. Place a ring of stone and earth around pipe.

From Which

A Fir 14" dia. bears N 3° W 17.8ft. scribed s1/16 S4 B.T.

A Fir 13" dia. bears S 26° E 13.0ft. scribed S1/16 S3 B.T.

Nailed brass washers stamped PLS 848, bearing tree and warning signs to each tree. Painted 6" red band around each tree.

Set steel posts with warning and boundry signs 5.0ft. South and 5.oft. East from corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Bayle
OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

Corner monumented 9-82
Witnessed by D. Mitchell Ferguson

Office of.....Surveyor..... County of... Grant
State of..... Oregon....., I hereby certify that the within instrument was filed in this office
for record on the...29th day of... August....., 1983
Robert D. Bayle by
(COUNTY OFFICIAL) (DEPUTY)