

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. E-7

History of original corner establishment:

In Sept. 1873, under GLO Contract No. 415 Samuel W. Lackland set basalt stone 13x8x8 inches 9 inches in ground for 1/4 Sec. cor. marked 1/4 on W. face, raised mound of stone alongside.

DIAGRAM

T12S R30E
S5
1/4 ———+———
S8

Description of corner evidence found:

A diligent search was made and no evidence of the original stone or mound could be found.

Description of monument and accessories I established to perpetuate the original location of this corner:

At single proportion location set 2½"x30" aluminum pipe with cap stamped:

Set pipe 24" in ground with mound of stone and dirt to cap.

Bearing trees:

A Lodgepole Pine 9" dia. bears S44°E, 22.7 ft. scribed 1/4 S8 BT.

A Tamarack 8" dia. bears N74W, 17.0 ft. scribed 1/4 S5 BT.

Attached 54-3 & 54-4 signs to both BT's. Attached brass washer stamped LS 1294 to foot blaze of both BT's. Painted blazes and 6" band around both BT's red.


Attached 54-4 sign to metal post 6 ft. East of corner.

T12S R30E
S5
1/4 ———+———
S8
1982
OR PLS 1294

Magnetic Declination = 19°30'E

I hereby certify the above corner monument was re-established as herein described on July 7, 1982.

Witnesses: R. Orton
G. Orton



Office of.....County Surveyor.....County of.....Grant
State of.....Oregon....., I hereby certify that the within instrument was filed in this office
for record on the...6... day of...Aug...1982...
Robert D. Baggett by
(COUNTY OFFICIAL) (DEPUTY)