

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. E-11

History of original corner establishment:

In Sept., 1881, under GLO Contract No. 415, Samuel W. Lackland set basalt stone 16x9x9 ins. 10 ins. in ground for 1/4 Sec. Cor. marked 1/4 on N. face, raised mound of stone alongside.

DIAGRAM

T12S R30E

1/4 S4
—+—
S9

Description of corner evidence found:

At approximate location calculated by traversing between the NW and NE corners of section 9 found remains of a mound of stones with several different types of stones and some fairly large stones. This evidence lends to the belief this is a man made mound which could not have been moved easily. Also found a 15x9"x8" stone with possible faint "4" on a face in the west side of the mound. A 40d spike set in place of the found stone.

Description of monument and accessories established to perpetuate the original location of this corner:

In place of 40d spike set 2 1/2" x 30" galvanized pipe with brass cap stamped:

T12S R30E

Set pipe 22" in ground with original stone buried alongside.
Built mound of stones to cap with original stones from original stone mound.

S4
1/4 —+—
S9

From which:

1981

A Grand Fir 12" dia. bears S75°W 42.6 ft. scribed

OR PLS 1294

1/4 S9 BT

A Grand Fir 14" dia. bears N40°E, 26.1 ft. scribed

1/4 S4 BT.

Attached 54-3 and 54-4 signs to both BT's. Attached brass washer stamped LS 1294 to foot blaze of both BT's. Painted blazes and 6" band around both BT's red. Attached 54-2 and 54-4 signs on metal post 5' West of corner. Attached 54-2 signs to metal posts 5' south and 5' East of corner.

Magnetic Declination = 19°30'E

I hereby certify the above corner monument was reestablished as herein described on July 2, 1981.

Witnesses: R. Orton
A. Hanley
G. Orton

Office of..... County Surveyor..... County of..... Grant.....
State of..... Oregon....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....
..... by
(COUNTY OFFICIAL) (DEPUTY)

