

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not preveously established

DIAGRAM

T12S R30E
C $\frac{1}{4}$
S11
1982
PLS 848

Description of corner evidence found:

Description of monument and accessories | established to perpetuate the original location of this corner:

Set a 30"x2" aluminum pipe with a 3 $\frac{1}{2}$ " aluminum Cap. stamped as shown in diagram, Set 20" in the ground.

From Which:

A Fir 10" dia. bears N30°E 3.3ft. scribed C $\frac{1}{4}$ S11 B.T.

A Pine 10" dia. bears N74°E 27.2ft. scribed C $\frac{1}{4}$ S11 B.T.

Nailed brass washers stamped PLS 848, B.T. & warning signs to each tree.

Painted 6" red band around each tree.

Set steel post with warning & boundry signs 10.0ft. East from corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

Corner monumented 10-10-82
Witnessed by D. Mitchell Ferguson

Office of.....Surveyor..... County of.....Grant.....
State of.....Oregon....., I hereby certify that the within instrument was filed in this office
for record on the.....29th day of.....August....., 1983.
.....by.....
(COUNTY OFFICIAL) (DEPUTY)