

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

DIAGRAM

T12S R30E
C $\frac{1}{4}$ S15
1982
PLS 848

Description of corner evidence found:

Corner not preveously established.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 30"x2" aluminum pipe with a 3 $\frac{1}{2}$ " aluminum Cap. stamped as shown in diagram, Set 25" in ground.

From Which:

A Fir 7" dia bears S25°E, 3.0ft. scribed C $\frac{1}{4}$ S15 B.T.

A Fir 7" dia. bears S42°W, 8.7ft. scribed C $\frac{1}{4}$ S15 B.T.

Nailed brass washers stamped PLS 848, bearing tree & warning signs to each tree. Painted 6" red band around each tree.

Set steel post with warning & bearing tree signs, North 4.0ft. from corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

Corner monumented 10-13-82

Witnessed by D. Mitchell Ferguson

Office of.....Surveyor..... County of.....Grant.....
State of.....Oregon....., I hereby certify that the within instrument was filed in this office
for record on the 29th day of.....August....., 19.....83.
.....Robert D. Sargent..... by
(COUNTY OFFICIAL) (DEPUTY)