

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established.

DIAGRAM

T12S R30E
SE1/16 S14
1983
PLS848
R.M.
2.0
↓

Description of corner evidence found:

Description of monument and accessories I established to perpetuate the original location of this corner:

Corner is on North side of a 18" Pine, corner point is a notch with brass washer stamped PLS848 on the North side of said Pine. Scribed SE1/16 S14 above notch.

From Which:

Set a 30"x2" aluminum pipe with 3½" aluminum cap, stamped as shown in diagram.

Set 18" in ground & raised a mound of stone around pipe, bears North 2.0 ft. from corner.

A Pine 16" dia. bears N35°W, 19.1 ft. from corner, scribed SE1/16 S14 BT.

A Juniper 10" dia. bears N50°E, 54.3 ft. from corner, scribed SE1/16 S14 BT.

Nailed brass washers stamped PLS848, bearing tree & warning signs to each tree.

Set steel posts with warning & boundry signs North & East 5 ft. from corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

Corner monumented 4-19-83

Witnessed by D. Mitdhell Ferguson

Office of.....Surveyor..... County of..... Grant.....
State of.....Oregon....., I hereby certify that the within instrument was filed in this office
for record on the....29th day of.....August....., 19....83.
.....by.....
(COUNTY OFFICIAL) (DEPUTY)