

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner originally established by Samuel W. Lackland under G.L.O. contract number 415, dated August 19, 1881. Surveyor General Record states;

Set post for corner from which:

A 12" tamarack bears S 32 E, 30 lks. dist.
A 10" fir bears N 58 W, 16 lks. dist.

DIAGRAM

T 12 S R 30 E

1/4 $\frac{S 17}{S 20}$

Description of corner evidence found:

Found the Northwest BT now a 16" white fir live and vigorous, scribing visible did not open.

Found rotted remains of a stump for the Southeast BT.

See map of survey dated July 1985

Description of monument and accessories I established to perpetuate the

original location of this corner: At record bearing and distance from the Northwest BT set a 2 1/2" x 30" aluminum pipe with aluminum cap 28" in the ground marked as shown from which:

NEW BT.


A 14" diameter white fir bears S22W, 23.3 feet marked 1/4 S20 BT.

ORIGINAL BT.

A 16" white fir bears N 58 W, 10.6 feet.

Set steel fencepost approximately 5' east with 54-2 and 54-4 sign and 5' west with a 54-2 sign.
Corner set May 31, 1985.

Witnesses; Rick Robinson Ray Crapo



OREGON
JULY 10, 1984
DUANE I. GRIFFITH
644

I used a steel tape and a magnetic compass in the establishment of these accessories. I used 20° East declination and the distance to the BTs are to the center of the tree. I set a brass washer marked OPLS 644 at the BT blaze. I painted a 6 inch band of red paint around all BTs and attached 54-3 and 54-9 signs.

Office of... *Surveyor* County of... *Grant*
State of... *Oregon* I hereby certify that the within instrument was filed in this office
for record on the... *15* day of... *July*, 19... *85*
... *Robert D. Crapo* by ...
(COUNTY OFFICIAL) (DEPUTY)