

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1881 by, S. W. Lackland, under General Land Office Contract No. 415 Surveyor Generals notes state: Set basalt stone 14 x 12 x 6, 9 inches in ground for $\frac{1}{4}$ section corner marked $\frac{1}{4}$ on West face, raised mound of stone $2\frac{1}{2}$ ft. high 4 ft. base alongside.

DIAGRAM

T12S R30E
S19 S20
1983
PLS 848

Description of corner evidence found:

No evidence found. Corner falls on steep rocky South slope.
No original accesories established, set position by proportion.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set a 30" x 2" aluminum pipe with $3\frac{1}{2}$ " aluminum cap, stamped as shown in diagram.
Set monument 12" in ground & raised mound of stone 16" high 40" in dia. around pipe.
From which:
A Pine 14" dia. bears S82°W, 32.1 ft. scribed $\frac{1}{4}$ S19 BT.
A Juniper 15" dia. bears N84°E, 39.8 ft. scribed $\frac{1}{4}$ S20 BT.
Nailed brass washers stamped PLS 848, Bearing Tree & warning signs to each tree.
Painted 6" red band around each tree.
Set steel post with boundary & warning sign South & West 5 ft. from corner

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Date May 20, 1983

Witnessed by Dan Martin

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

Office of.....Surveyor..... County of.....Grant.....
State of.....Oregon....., I hereby certify that the within instrument was filed in this office
for record on the.....29th..... day of.....August....., 1983.
Robert D. Baggett by
(COUNTY OFFICIAL) (DEPUTY)