

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1869 by John B.. David, Under General Land Office Contract No. 131. Surveyor Generals Notes State:
Set stone 14x10x10" for $\frac{1}{4}$ section corner.

DIAGRAM

T12S
R30E R31E
 $\frac{1}{4}$
S24 S19
1983
PLS848

Description of corner evidence found:

No evidence found old fenceing activity in the area.
No accessories originally established.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 30"x2" aluminum pipe with a 3 $\frac{1}{2}$ " aluminum cap stamped as shown in diagram.
Set 6" in the ground & raised a mound of stone & earth around pipe.



From which:

A Pine 9" dia. bears S84°W, 34.0 ft. scribed $\frac{1}{4}$ S24 BT.

A " 6" " " N62 $\frac{1}{2}$ °E, 56.9 ft. " " S19 BT.

Set steel post with warning sign, in mound, 1 ft. North from pipe.

Nailed brass washers stamped PLS848, bearing tree & warning signs to each tree.



Corner monumented 7-28-83

Witnessed by Jeff Smith

Office of...Surveyor..... County of...Grant.....
State of...Oregon....., I hereby certify that the within instrument was filed in this office
for record on the 29th day of August, 1983.
Robert D. Bayart by
(COUNTY OFFICIAL) (DEPUTY)