

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1881 by S. W. Lackland, under General Land Office Contract No. 415 Surveyor Generals notes state: Set basalt stone 18 x 9xx 9 ins. 12 ins. in ground for $\frac{1}{4}$ sec cor. marked $\frac{1}{4}$ on N-Face raised mound of stone alongside.

DIAGRAM

T12S R30E
 $\frac{1}{4}$ $\frac{S19}{S30}$
1083
PLS 848

Description of corner evidence found:

No evidence found. Logging in area has destroyed all traces. No original accesories established set position by proportion.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set a 30" x 2" aluminum pipe with 3 $\frac{1}{2}$ " aluminum cap, stamped as shown in diagram.

Set monument 27" in ground.

From which:

A Pine 16" dia. bears N72°W, 6.0 ft. scribed $\frac{1}{4}$ S19 BT.

A Pine 14" dia. bears S48°W, 25.6 ft. scribed $\frac{1}{4}$ S30 BT.

Nailed brass washers stamped PLS 848, bearing tree & warning signs on each tree.

Painted 6" red band around each tree.

Set steel posts with boundary & warning signs 3 ft. east & west from corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Date May 20, 1983

Witnessed by Dan Martin

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

Office of.....Surveyor..... County of.....Grant.....

State of.....Oregon....., I hereby certify that the within instrument was filed in this office

for record on the...29th day of.....August....., 19..83.

Robert D. Bager
(COUNTY OFFICIAL) (DEPUTY)