

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1881 by S. W. Lackland, under General Land Office Contract No 415. Surveyor General's notes state: Set basalt stone 15 x 12 x 12 ins. 10 ins. in ground for $\frac{1}{4}$ section corner marked $\frac{1}{4}$ on N-Face. Raised mound of stone along side.

DIAGRAM

T12S R30E
 $\frac{1}{4}$ S20
S29
1983
PLS 848

Description of corner evidence found:

No evidence found. Corner falls in small steep draw, that shows substantial erosion. Corner has apparently washed down hill.

No original accessories established.
Position established by proportion.

Description of monument and accessories established to perpetuate the original location of this corner:

Set a 30" x 2" aluminum pipe with 3 $\frac{1}{2}$ " aluminum cap, stamped as shown in diagram.
Set monument 12" in ground raised mound of stone around pipe.
From which:
A Juniper 10" dia. bears N87 $\frac{1}{2}$ °E 23.2 ft. scribed $\frac{1}{4}$ S20 BT.
A Juniper 35" dia. bears S34°W 41.5 ft. scribed $\frac{1}{4}$ S29 BT.
Nailed brass washers stamped PLS 848 Bearing Tree & warning signs to each tree.
Painted 6" red band around each tree.
Set steel post with boundary and warning signs 5 ft. E & W from corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Date May 18, 1983

Witnessed by Don Martin

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

Office of.....Surveyor..... County of..... Grant.....
State of.....Oregon....., I hereby certify that the within instrument was filed in this office
for record on the.....29th day of.....August....., 19.....83.
Robert D. Beyer
(COUNTY OFFICIAL) (DEPUTY)