

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1881 by S.W. Lackland, under General Land Office Contract No. 415, Surveyor Generals Notes State:
Set basalt stone 17x12x8ins. 13ins. in ground for $\frac{1}{4}$ Sec. Cor.
marked $\frac{1}{4}$ on N face. Raised mound stone alongside.

DIAGRAM

T12S R30E
S21
 $\frac{1}{4}$ — • —
S28
1982
PLS 848

Description of corner evidence found:

None evidence found. Set corner by proportion.
Set corner by proportion.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set a 30"x2" aluminum pipe with a 3 $\frac{1}{2}$ " aluminum Cap. stamped as shown in diagram. Set 25" in ground.

From Which:

A Fir 11" dia. bears S70°W 20.6ft. scribed $\frac{1}{4}$ S28 B.T.

A Pine 8" dia. bears N19°W 10.7ft. scribed $\frac{1}{4}$ S21 B.T.

Nailed brass washers stamped PLS 848, warning & bearing tree signs to each tree. Painted 6" red band around each tree.

Set steel posts with warning & boundry signs, North & West 3.0ft. from corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

Corner monumented 10-26-82

Witnessed by D. Mitchell Ferguson

Office of.....Surveyor..... County of...Grant.....
State of.....Oregon....., I hereby certify that the within instrument was filed in this office
for record on the 29th day of.....August....., 1983.

..... by
(COUNTY OFFICIAL) (DEPUTY)