

**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**History of original corner establishment:**

Corner established in 1881 by S.W. Lackland, Under General Land Office Contract No. 415. Surveyor Generals Notes State: Set baslat stone 16x14x9 in. 10 in. in the ground for corner to sections 21,22,27,&28 marked 2 notches on S and 3 notches on E edges. Raised a mound of stone 2½ ft. high & 5 ft. base along side.

**DIAGRAM**

T12S R30E  
S21 | S22  
S28 | S27  
1983  
PLS848

**Description of corner evidence found:**

No evidence found, corner falls on steep East slope. Corner probably rolled down hill.  
No original accessories established. Set position by proportion.

**Description of monument and accessories | established to perpetuate the original location of this corner:**

Set a 14"x2" aluminum pipe with a 3½" aluminum cap, stamped as shown in diagram. Set on solid rock & raised a mound of stone 3 ft. dia. around pipe.  
From Which:  
A Pine 9" dia. bears N7°W, 18.9 ft. scribed T12S R30E S21 BT.  
A " 15" " " N20°E, 43.2 ft. " " " S22 BT.  
A " 14" " " S27°E, 29.2 ft. " " " S27 BT.  
A steel post bears S45°W, 4.2 ft. warning & bearing tree sign attached to each post. Nailed brass washer stamped PLS848, bearing tree & warning signs to each tree. Painted 6" red band around each tree.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Douglas M. Ferguson*  
OREGON  
JULY 12, 1968  
DOUGLAS M. FERGUSON  
848

Corner Monumented 5-13-83

Witnessed by Dan Martin

Office of.....Surveyor..... County of.....Grant.....  
State of.....Oregon....., I hereby certify that the within instrument was filed in this office  
for record on the...29th day of.....August....., 19...83.  
*Robert D. Baggett* by .....  
(COUNTY OFFICIAL) (DEPUTY)