

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1881 by, S.W. Lackland, Under General Land Office Contract No. 415 Surveyor Generals Notes State:
Set basalt stone 16x7x6 in. 10 in. in the ground for $\frac{1}{4}$ section cor. marked $\frac{1}{4}$ on N face.

From Which:

A Pine 7 in. dia. bears $N45^{\circ}E$, 26 lks. marked $\frac{1}{4}$ S BT.

A Pine 8 in. dia. bears $S2^{\circ}W$, 18 lks. dist. marked $\frac{1}{4}$ S BT.

DIAGRAM

T12S R30E

$\frac{1}{4}$ $\frac{S23}{S26}$

1983

PLS848

Description of corner evidence found:

A concentrated search at mid-point between cor. $\frac{1}{2}$ mile East & West, revealed no evidence, also made searches assuming the corner was stubed from each direction, with no evidence found.

After searching as described above, & over a wide area, no evidence is found, no activity in the area should have disturbed this corner

it is possible that it was never set. Reluctantly this corner is positioned by proportion from corners $\frac{1}{2}$ mile East & West.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set a 30"x2" aluminum pipe with a 3 $\frac{1}{2}$ " aluminum cap, stamped as shown in diagram. Set 24" in the ground.

From Which:

A Pine 8" dia. bears $N50^{\circ}W$, 7.2 ft. scribed $\frac{1}{4}$ S23 BT.

A Juniper 9" dia. bears $S38^{\circ}W$, 49.4 ft. scribed $\frac{1}{4}$ S26 BT.

Nailed brass washers stamped PLS848, bearing trees & warning signs to each tree.

Set a steel posts with warning sign 2 ft. North from corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

Corner monumented 5-4-83

Witnessed by Dan Martin

Office of.....Surveyor..... County of.....Grant.....
State of.....Oregon....., I hereby certify that the within instrument was filed in this office
for record on the 29th day of.....August....., 1983.

Robert D. Baggett by
(COUNTY OFFICIAL) (DEPUTY)