

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1869 by John B. David, Under General Land Office Contract No. 131. Surveyors' Notes State:
Set stone 14x12x8" for corner to sections 24, 25, 19, & 30.
In 1881, under G.L.O. contract No. 415, S.W. Lockland repaired corner by raising a mound of stone.

DIAGRAM

T12S
R30E R31E
S24 | S19
S25 | S30
1983
PLS848

Description of corner evidence found:

No evidence found, corner falls on edge of old primitive road up Grouse Creek.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set a 30"x2" aluminum pipe with a 3½" aluminum cap stamped as shown in diagram. Set 20" in the ground & placed a ring of stone around pipe.

From Which:

A Juniper 8" dia. bears N14°45'W, 94.8 ft. scribed T12S R30E S24 BT.
A Pine " " " N23°E, 37.5 ft. scribed " R31E S19 BT.
A Fir 16" " " S73°E, 45.5 ft. " " S30 BT.
A Pine 10" " " S88°W, 111.1 ft. " " R30E S25 BT.

Set steel post with warning sign North 3 ft.

Nailed brass washers stamped PLS848, bearing tree & warning signs to each tree.



Corner monumented 7-28-83

Witnessed by Jeff Smith

Office of Surveyor..... County of... Grant.....
State of Oregon....., I hereby certify that the within instrument was filed in this office
for record on 29th day of August....., 19..83
by (COUNTY OFFICIAL) (DEPUTY)