

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1881 by, S. W. Lackland, under General Land Office Contract No. 415 Surveyor Generals notes state: Set basalt stone 16 x 12 x 8 ins. 10 ins. in ground for $\frac{1}{2}$ section corner marked $\frac{1}{2}$ West face, raised mound of stone along side.

DIAGRAM

T12S R30E
S30 S29
1983
PLS 848

Description of corner evidence found:

No evidence found. Corner falls along skid trail in logged off area.
No original accessories established set position by proportion.

Description of monument and accessories established to perpetuate the original location of this corner:

Set a 30" x 2" aluminum pipe with 3 $\frac{1}{2}$ " aluminum cap, stamped as shown in diagram.
Set monument 20" in ground, placed ring of stone around pipe.
From which:
A Pine 6" dia. bears N13°W, 15.5ft. scribed $\frac{1}{4}$ S30 BT.
A Fir 7" dia. bears S17°E, 15.7 ft. scribed $\frac{1}{4}$ S29 BT.
Nailed brass washer stamped PLS 848, Bearing Tree & Warning signs to each tree.
Painted 6" red band around each tree.
Set steel post with boundary & warning signs 3 ft. North & 4 ft. South from corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Date May 18, 1983

Witnessed by Dan Martin

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

Office of.....Surveyor..... County of.....Grant.....

State of..Oregon....., I hereby certify that the within instrument was filed in this office

for record on the 29th day of.....August....., 1983..

Robert D. Bager by
(COUNTY OFFICIAL) (DEPUTY)