

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established.

DIAGRAM

T12S	R30E
C $\frac{1}{2}$	S26
1983	R.M.
PLS848	13.8

Description of corner evidence found:

Description of monument and accessories established to perpetuate the original location of this corner:

Set a 5/8 iron pin with 1" aluminum cap, stamped PLS848, on South edge of Grouse Creek.
From Which:

Set a 30"x2" aluminum pipe with 3 $\frac{1}{2}$ " aluminum cap, stamped as shown in diagram.

Set 28" in ground. Bears South on center section line 13.8 ft.

A Fir 10" dia. bears N88°W, 17.0 ft. scribed C $\frac{1}{2}$ S26 BT.

A Fir 12" dia. bears N53°E, 20.7 ft. scribed C $\frac{1}{2}$ S26 BT.

Nailed brass washers stamped PLS848, bearing tree & warning signs to each tree.

Set steel posts with boundry signs & warning signs 2' S & W from corner position.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

Corner monumented 4-28-83
Witnessed by Dan Martin

Office of.....Surveyor..... County of.....Grant.....

State of...Oregon....., I hereby certify that the within instrument was filed in this office
for record on the 29th. day of.....August....., 1983.

Robert D. Sargent by
(COUNTY OFFICIAL) (DEPUTY)