

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1881 by S.W. Lackland, Under General Land Office Contract No. 415. Surveyor Generals Notes State:
Set a basalt stone 15"x9"x8", 12" in the ground for $\frac{1}{4}$ section corner marked $\frac{1}{4}$ on N face, raised a mound of stone 2 ft. high and 4 ft. base alongside.

DIAGRAM

T12S R30E
S26
 $\frac{1}{4}$ — . —
S35
1983
PLS848

Description of corner evidence found:

Corner is on East slope on rocky ground. E/W fence running through the area. Fencing activity has destroyed all evidence.
Set position by proportion.

Description of monument and accessories established to perpetuate the original location of this corner:

Set a 30"x2" aluminum pipe with a 3 $\frac{1}{2}$ " aluminum cap, stamped as shown in diagram. Set 16" in the ground & raised a mound of earth and stone around pipe.
From Which:
A Pine 8" dia. bears N3°W, 10.6 ft. scribed $\frac{1}{4}$ S26 BT.
A Juniper 20" dia. bears S65°W, 4.6 ft. scribed $\frac{1}{4}$ S35 BT.
Nailed brass washers stamped PLS848, with bearing tree & warning signs to each tree.
Set steel posts with boundry & warning signs on each tree.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

Corner monumented 4-20-83

Witnessed by D. Mitchell Ferguson

Office of.....Surveyor..... County of..... Grant
State of.....Oregon....., I hereby certify that the within instrument was filed in this office
for record on the...29th...day of.....August.....1983.
.....Robert D. Ferguson..... by
(COUNTY OFFICIAL) (DEPUTY)