


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:


Original corner established by: John B. David, Deputy Surveyor, under Contract No. 131, dated June 8, 1869.

Surveyor General Record States: Set stone 16x8x7 inches, for 1/4 section corner.



Description of corner evidence found:

Found aluminum monument from Survey No. 1185, S30°27'W, 9.71 ft. and an aluminum monument from Survey No. 1525, N50°02'W, 8.05 ft. both corner positions are rejected, see survey narrative.



See Record Map of Survey No. 1645

Description of monument and accessories set at corner location:

At the corner position determined by single proportion I set a 2½"x30" aluminum pipe with attached 3½" aluminum cap, 30 inches in the ground, surrounded by a mound of stone. The cap is stamped as shown in the diagram.

From which:

A 5/8" iron pin bears N14°E, 14.84 feet, with attached yellow plastic cap marked PLS848.

A 5/8" iron pin bears S75°E, 4.73 feet, with attached yellow plastic cap marked PLS848.

A 5/8" iron pin bears S83°W, 11.79 feet, with attached yellow plastic cap marked PLS848.

A 5/8" iron pin bears N39°W, 20.78 feet, with attached yellow plastic cap marked PLS848.

I used a steel tape and true bearings based on survey number 1645 to tie corner references.

Date: September 13, 2002

Office of Surveyor County of Grant
State of Oregon I hereby certify that the within instrument was filed in this office
for record on the 17 day of Sept, 2002.
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)