

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1869 by J. B. David, under General Land Office Contract No. 131. Surveyor Generals notes state: Set stone 15 x 10 x 8 for corner to sections 32 & 33.

DIAGRAM

T12S	R30E
S32	S33
S5	S4
1983	
PLS	848

Description of corner evidence found:

No evidence found. Fencing activity in area, may have destroyed corner.
Searched for 30" line tree called by Lackland
Logging has removed tree.
No original accessories established set position by proportion.

Description of monument and accessories established to perpetuate the original location of this corner:

Set a 30" x 2" aluminum pipe with 3½" aluminum cap, stamped as shown in diagram.
Set monument 12" in ground, raised mound of stone around pipe.
From which:
A Juniper 9" dia. bears N47°W 26.8 ft. scribed T12S R30E S32 BT.
A Juniper 4" dia. bears N35°E, 16.5 ft. scribed S33 BT.
A Mahogany 5" dia. bears S85°E, 91.8 ft. scribed S4 BT.
A Mahogany 7" dia. bears S78°W, 53.4 ft. scribed T13S R30E S5 BT.
Nailed brass washers stamped PLS 848, Bearing Tree & warning signs to each tree.
Painted 6" red band around each tree.
Set steel post with warning sign 5 ft. North of corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Date May 17, 1983

Witnessed by Dan Martin

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

Office of.....Surveyor..... County of.....Grant.....
State of.....Oregon....., I hereby certify that the within instrument was filed in this office
for record on the 29th day of.....August....., 1983.
Robert D. Baggett by
(COUNTY OFFICIAL) (DEPUTY)