

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. C-7

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T12S R31E
C1/4
S5
1986
PLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 15" in the ground and raised a small mound of stone filled with earth around the pipe.

From Which:

A Juniper 9" dia., Bears N 7⁰E., 38.0 ft., scribed: C1/4 S5 BT

A Juniper 7" dia., Bears S23⁰E., 22.1 ft., scribed: C1/4 S5 BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, East & West 6 ft. from the corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1969
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.
On: July 7, 1986
Refer to Map of Survey No. 941

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 30 day of Sept, 1986
Robert D. Dugan by _____
(COUNTY OFFICIAL) (DEPUTY)