

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. C-11

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T12S R31E
C1/4
S4
1986
PLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 8" in the ground and raised a mound of stone & earth around pipe.

From Which:

A Juniper 20" dia., Bears North 17.2 ft., scribed: C1/4 S4 BT

A Juniper 8" dia., Bears S28°W., 47.2 ft., scribed: C1/4 S4 BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence post with warning Sign, West alongside pipe, in stone and earth mound.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1986
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.
On: July 14, 1986
Refer to Map of Survey No. 941

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 30 day of August, 1986
Robert D. Degehl by _____
(COUNTY OFFICIAL) (DEPUTY)