

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. D-5

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T12S R31E
S1/16
S6/55
1986
PLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 12" in the ground and raised a mound of stone & earth around the pipe.

From Which:

A Juniper 12" dia., Bears S23°10'E., 19.3 ft., scribed: S1/16 S5 BT
A forked Juniper 10" dia., Bears N20°53'W., 107.0 ft., scribed: S1/16 S6 BT
Measurements to trees taken with an electronic tacheometer, with angles turned from the survey control network.
Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, North & East 8 ft. from the corner.

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.
On: July 10, 1986
Refer to Map of Survey No. 941

Office of.....*Surveyor*..... County of.....*Grant*.....
State of.....*Oregon*..... hereby certify that the within instrument was filed in this office
for record on the.....*30*..... day of.....*Sept*....., 19.....*86*.....
.....*Douglas M. Ferguson*..... by.....
(COUNTY OFFICIAL) (DEPUTY)