


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner originally established by John B. David under GLO contract number 131 dated June 8, 1869. Surveyor General record states:

Set stone 16x10x8 for $\frac{1}{4}$ Sec corner



No record of subsequent remonumentation was found in the Grant County records

Description of corner evidence found:

Found Stone 15x10x6 marked $\frac{1}{4}$

See map of survey dated January, 1985

Description of monument and accessories I established to perpetuate the original location of this corner: In place of stone, I set a $2\frac{1}{2}$ inch x 30 inch aluminum pipe with aluminum cap marked as shown, 24 inches in the ground, from which:


New BTs

A 10 inch diameter P.Pine bears N58°E 11.8 feet marked $\frac{1}{4}$ S15 BT
A 12 inch diameter P.Pine bears S48°W 17.5 feet marked $\frac{1}{4}$ S22 BT

Buried the original stone West and alongside of monument
Raised mound of stone around monument

Set steel fenceposts approximately 5 feet West with 54-2 sign
and approximately 5 feet South with 54-2 and 54-4 signs

Corner set August 24, 1984
Witness: Mike Wagner



REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 10, 1964
DUANE I. GRIFFITH
644

I used a steel tape and magnetic compass in the establishment of these accessories. I used 20° East magnetic declination and the distance to the BTs are to the center of the tree. I set a brass washer marked OPLS 644 at the BT blaze. I painted a 6 inch red band around all BTs and attached 54-3 and 54-4 signs.

Office of.....*Surveyor*..... County of.....*Grant*.....
State of.....*Oregon*..... I hereby certify that the within instrument was filed in this office
for record on the.....*11*..... day of.....*Jan*....., 19.....*85*.....
.....*Duane I. Griffith*..... by.....*Mike Wagner*.....
(COUNTY OFFICIAL) (DEPUTY)