

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1869, by J.B. David, Under General Land Office Contract No. 131; Surveyor Generals Notes State:
Set stone 18x6x6 for corner to sections 31&32

DIAGRAM

T12S R31E
S31 | S32
S6 | S5
T13S
1982
PLS848

Description of corner evidence found:

No evidence found, fencing activity has destroyed all traces.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set a 30"x2" aluminum pipe with a 3½" aluminum cap; stamped as shown in diagram.
Set 16" in the ground & raised a mound of stone around pipe;
From Which:
A Juniper 5" dia bears N22°W, 94.6 ft. scribed T12S R31E S31 BT.
A Forked Juniper 10" " " N16°E 89.8 ft. " " " S32 ".
A Juniper 12" " " S32°W; 239.9 ft. " T13S " S6 ".
A steel postsbears South 3.8 ft.
Naøled brass washers stamped PLS848; bearing tree & warning signs to each tree.
Painted 6" red band around each tree.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

Corner Monumented 11/82
Witnessed by D. Mitchell Ferguson

Office of.....Surveyor..... County of..Grant.....
State of.....Oregon....., I hereby certify that the within instrument was filed in this office
for record on the 29th day of August, 1983.
.....by.....
(COUNTY OFFICIAL) (DEPUTY)