


History of original corner establishment:

Corner established in 1881 by Robb and Gradon under General Land Office Contract No. 383.
Surveyor General Record states;

Set post for $\frac{1}{4}$ section corner from which;

A pine 8" in diameter bears N 27° W, 13 links dist.

A fir 24" in diameter bears N 60° E, 21 links dist.



No record of subsequent remonumentation was found in county records.
Description of corner evidence found:

None. Area lands in skid road from logging operation.

See map of survey dated September, 1980.
Description of monument and accessories established to perpetuate the original location of this corner:


At proportionate distance I set 2 $\frac{1}{2}$ " x 30" aluminum monument marked as shown 28" in ground from which:

NEW BT's

A 14" fir bears N 50° E, 46.5 ft marked T12S R33E $\frac{1}{4}$ S6 BT

A 21" fir bears S 73° W, 22.3 ft marked T12S R32E $\frac{1}{4}$ S1 BT

Raised mound of stone



REGISTERED
PROFESSIONAL
LAND SURVEYOR

Duane I. Griffith

OREGON
JULY 10, 1964
DUANE I. GRIFFITH
644

Brass washer nailed to BT blaze.
Used steel tape and magnetic compass
with 15° East declination.
Measured to center of new B.T.s

Office of.....*Surveyor*..... County of.....*Grant*.....
State of.....*Oregon*....., I hereby certify that the within instrument was filed in this office
for record on the.....*31*..... day of.....*Oct*....., 19.....*80*.....
.....*Robert L. Baggett*..... by.....
(COUNTY OFFICIAL) (DEPUTY)