

History of original corner establishment:


Corner established in 1881 by Robb and Gradon under General Land Office Contract No. 383.

Surveyor General Record states;

Set post for 1 $\frac{1}{4}$ section corner from which;

A pine 3" diameter bears N 45° W, 12 links dist.

A pine 3" diameter bears S 17° E, 16 links dist.



No record of subsequent remonumentation was found in county records.
Description of corner evidence found:

None, area has been logged.



See map of survey dated September, 1980.
Description of monument and accessories established to perpetuate the original location of this corner:

At proportionate distance I set 2 $\frac{1}{2}$ " x 30" aluminum monument marked as shown 27" in ground from which;

NEW BTs

A 10" fir bears N 68° E, 9.8 ft marked $\frac{1}{4}$ S2 BT

A 12" tamarack bears S 39 E, 24.9 ft marked $\frac{1}{4}$ S11 BT



Brass washer nailed to BT blaze.
Used steel tape and magnetic compass with 15° East declination.
Measured to center of new B.T.s

Office of.....*Surveyor*..... County of.....*Grant*.....
State of.....*Oregon*..... I hereby certify that the within instrument was filed in this office
for record on the.....*31*..... day of.....*Oct*....., 19*80*
.....*Robert D. Baggett*..... by.....
(COUNTY OFFICIAL) (DEPUTY)