


History of original corner establishment:
Corner not set in original survey.

I established this 1/16 corner at midpoint and on line between the corner 1/4 corner and the North 1/4 corner of this section



No record of subsequent monumentation found in County records.
Description of corner evidence found:

None

See map of survey dated September, 1980.

Description of monument and accessories I established to perpetuate the original location of this corner:




At intersection I set 2 1/2" x 30" aluminum monument marked as shown 27" in ground from which;

NEW BTs

A 14" fir bears S 24° W, 14.0 ft marked CN1/16 S11 BT

A 14" p pine bears N 21° W, 13.0 ft marked CN1/16 S11 BT

Raised mound of stone



Brass washer nailed to BT blaze.
Used steel tape and magnetic compass with 15° East declination.
Measured to center of new B.T.s

Office of..... Surveyor County of..... Grant
State of..... Oregon I hereby certify that the within instrument was filed in this office
for record on the..... 31..... day of..... Oct....., 1980
Robert D. Sargent by.....
(COUNTY OFFICIAL) (DEPUTY)