


History of original corner establishment:

Corner established in 1881 by Robb and Gradon under
General Land Office Contract No. 383.
Surveyor General Record states;

Set stone 12" x 12" 5" for $\frac{1}{4}$ section corner from which;

A pine 9" diameter bears S 28° W, 47 links dist.

A pine 14" diameter bears S 38° E, 112 links dist.



No record of subsequent remonumentation was found in county records.
Description of corner evidence found:
Found both BTs, no stone found

See map of survey dated September, 1980.
Description of monument and accessories established to perpetuate the
original location of this corner:

At intersection of call distances from BTs I set 2 $\frac{1}{2}$ ' x 30" aluminum monument
marked as shown 28" in ground from which;




ORIGINAL BTs

A 24" pine stump bears S 38° E, 73.9 ft to face of BT, scribes visible

A 22" p pine bears S 28° W, 31.0 ft to face of BT, live vigorus, scribes visible

NEW BT

A 12" p pine bears S 60° E, 26.6 ft marked $\frac{1}{4}$ S11 BT



Brass washer nailed to BT blaze.
Used steel tape and magnetic compass
with 15° East declination.
Measured to center of new B.T.s

Office of... Surveyor County of... Grant
State of... Oregon I hereby certify that the within instrument was filed in this office
for record on the... 31 day of... OCT 19... 80
Robert M. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)