
History of original corner establishment:
Corner not set in original survey.

I established this 1/16 corner at midpoint and on line between the center ¼ corner and the East ¼ corner of this section.

DIAGRAM
T12S R32E



No record of subsequent monumentation found in County records.
Description of corner evidence found:

None

See map of survey dated September, 1980.
Description of monument and accessories I established to perpetuate the original location of this corner:

At intersection I set 2½" x 30" aluminum monument marked as shown 20" in ground from which;

NEW BTs

A 14" juniper bears N 59° E, 55.5 ft marked CE1/16 S11 BT

A 8" juniper bears N 72° W, 25.6 ft marked X BT

Raised mound of stone

T12S R32E
E 1/16
C — C
S 11
1980
OPLS 644

REGISTERED PROFESSIONAL LAND SURVEYOR
OREGON
JULY 10, 1964
DUANE I. GRIFFITH
644

Brass washer nailed to BT blaze.
Used steel tape and magnetic compass with 15° East declination.
Measured to center of new B.T.s

Office of SURVEYOR County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office for record on the 31 day of Oct, 19 80
Robert D Bagett by
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

☆GPO—798-276

35/19

G-20