


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner originally established by John B. David under GL0 contract number 131, dated June 8, 1869.

Surveyor General record states:

Set stone 20x10x5 for $\frac{1}{4}$ Sec corner



Description of corner evidence found:

Found stone 22x13x5, face down, marked $\frac{1}{4}$ with one stone alongside

Description of monument and accessories I established to perpetuate the

original location of this corner: In place of stone, I set a $2\frac{1}{2}$ " x 30" aluminum pipe with aluminum cap marked as shown, 24 inches in the ground, from which:

New BTs

- A 16 inch diameter P.Pine bears North 47° East, 10.9 feet, marked $\frac{1}{4}$ S19 BT
- A 17 inch diameter P.Pine bears North 68° West, 20.3 feet, marked $\frac{1}{4}$ S24 BT

I buried the original stone North and alongside of the new monument

Raised mound of stone around new monument



Attached 54-4 signs and bearing tree tags to and painted a 6 inch red band around all bearing trees

Set a steel fence post approximately 5 feet North with 54-4 sign attached

Corner set October 12, 1983

Witnesses: Greg Blackman and Rick Robinson

See survey number 792



I used a steel tape and magnetic compass in the establishment of these accessories. I used $17\frac{1}{2}^{\circ}$ East magnetic declination, and the distances to the new BTs are to the center of the tree. I attached a brass washer marked OPLS 644 by the BT blaze of the new BTs.

Office of.....*Surveyor*..... County of.....*Grant*.....
State of.....*Oregon*....., I hereby certify that the within instrument was filed in this office
for record on the.....*30*..... day of.....*Nov*....., 19*83*.....
Robert D. Buzott by.....
(COUNTY OFFICIAL) (DEPUTY)