

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established

DIAGRAM

T12S R32E

C $\frac{1}{4}$

.

S 19

Description of corner evidence found:

NONE

Description of monument and accessories I established to perpetuate the

original location of this corner: At corner position, I set a 2 $\frac{1}{2}$ " x 30" aluminum pipe with aluminum cap marked as shown, 26 inches in the ground, from which:

New BTs

A 8 inch diameter double bole Juniper bears South 39° East, 16.6 feet, marked C $\frac{1}{4}$ S19 BT
A 10 inch diameter P.Pine bears South 49° West, 15.3 feet, marked C $\frac{1}{4}$ S19 BT

Raised mound of stone around new monument

Attached 54-9 signs and bearing tree tags to and painted a 6 inch red band around all bearing trees

Set steel fence post approximately 5 feet North with 54-9 sign

Corner set October 22, 1983

Witness: Rick Robinson

See survey number 792

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 10, 1934
DUANE I. GRIFFITH
644

T12S R32E

C $\frac{1}{4}$

.

S 19

1983

OPLS 644

I used a steel tape and magnetic compass in the establishment of these accessories. I used 17 $\frac{1}{2}$ ° East magnetic declination, and the distances to the new BTs are to the center of the tree. I attached a brass washer marked OPLS 644 by the BT blaze of the new BTs

Office of... Surveyor ... County of... Grant ...
State of... Oregon ... I hereby certify that the within instrument was filed in this office
for record on the... 30 day of... Nov ... 19... 83

(COUNTY OFFICIAL)

(DEPUTY)