


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner originally established by John B. David under GLO contract number 131, dated June 8, 1869.

Surveyor General record states:

Set stone 16x9x6 for $\frac{1}{4}$ Sec corner



Description of corner evidence found:

Found stone of called size, with faint marks, in mound of stone


Description of monument and accessories I established to perpetuate the

original location of this corner: In place of stone, I set a $2\frac{1}{2}$ " x 30" aluminum pipe with aluminum cap marked as shown, 24 inches in the ground, from which:

New BTs

A 16 inch diameter P.Pine bears North 46° East, 16.5 feet, marked $\frac{1}{4}$ S20 BT
A 12 inch diameter P.Pine bears North 43° West, 4.8 feet, marked $\frac{1}{4}$ S19 BT

Buried the original stone South and alongside of the new monument
Raised mound of stone around new monument
Attached 54-4 signs and bearing tree tags to and painted a 6 inch red band around all bearing trees
Set steel fence post approximately 5 feet North with 54-4 sign
Corner set October 13, 1983
Witnesses: Greg Blackman and Rick Robinson
See survey number 792



REGISTERED
PROFESSIONAL
LAND SURVEYOR

Duane I. Griffith

OREGON
JULY 10, 1984
DUANE I. GRIFFITH
644

I used a steel tape and magnetic compass in the establishment of these accessories. I used $17\frac{1}{2}^{\circ}$ East magnetic declination, and the distances to the new BTs are to the center of the tree. I attached a brass washer marked OPLS 644 by the BT blaze of the new BTs

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 30 day of Nov, 1983
Robert D. Bazzett by _____
(COUNTY OFFICIAL) (DEPUTY)