


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner originally established by John B. David under GLO contract number 131, dated June 8, 1869.

Surveyor General record states;

Set stone 17x12x $\frac{1}{4}$ for $\frac{1}{4}$ Sec corner



Description of corner evidence found:

Found marked stone, called size, loose on ground

Description of monument and accessories I established to perpetuate the

original location of this corner: In place of stone, I set a 2 $\frac{1}{2}$ " x 30" aluminum pipe with aluminum cap marked as shown, 28 inches in the ground, from which:

New BTs

A 11 inch diameter tamarack bears North 58° East, 59.2 feet, marked $\frac{1}{4}$ S22 BT

A 20 inch diameter P.Pine bears North 38° West, 34.7 feet, marked $\frac{1}{4}$ S21 BT

Buried the original stone South and alongside of new monument


Attached 54-4 signs and bearing tree tags to and painted a 6 inch red band around all bearing trees

Set steel fence post approximately 5 feet North with 54-4 sign

Corner set October 13, 1983

Witnesses: Greg Blackman and Rick Robinson

See survey number 792



I used a steel tape and magnetic compass in the establishment of these accessories. I used 17 $\frac{1}{2}$ ° East magnetic declination, and the distances to the new BTs are to the center of the tree. I attached a brass washer marked OPLS 644 by the BT blaze of the new BTs

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 30 day of Nov, 1983
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)