

History of original corner establishment:


Corner established in 1869 by John B. David under
General Land Office Contract No. 131.

Surveyor General Record states;

Set stone 17" x 10" x 5" for $\frac{1}{4}$ section corner

DIAGRAM

T12S R33E



No record of subsequent remonumentation was found in County records.

Description of corner evidence found:

None

See map of survey dated September, 1980.


Description of monument and accessories I established to perpetuate the
original location of this corner:

At proportionate distance I set 2 $\frac{1}{2}$ ' x 30" aluminum monument marked as shown
29" in ground from which;



NEW BTs

A 15" p pine bears N 41° E, 55.1 ft marked T12S R33E $\frac{1}{4}$ S19 BT

A 10" fir bears N 58° W 47.7 ft marked T12S R32E $\frac{1}{4}$ S24 BT



Duane I. Griffith



Brass washer nailed to BT blaze.
Used steel tape and magnetic compass
with 15° East declination.
Measured to center of new B.T.s

Office of *Surveyor* County of *Grant*
State of *Oregon*, I hereby certify that the within instrument was filed in this office
for record on the *31* day of *Oct*, 19*80*
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)